## United States of America

## Department of Transportation -- Hederal Abiation Administration

## Supplemental Type Certificate

Number SA04369CH

This certificate issued to

Kelly Aerospace Thermal Systems LLC 1625 Lost Nation Road Wiloughby, OH 44094

certifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Part 23 of the Federal Aviation Regulations. (See Type Certificate Data Sheet No. A4CE for complete certification basis)

Original Product - Type Certificate Number:

A4CE

Make:

Textron Aviation Inc.

Model:

206H, T206H

Description of Type Design Change:

Installation of a backup alternator system, Kelly Aerospace kit number KATS-15-002 in accordance with Kelly Aerospace Installation Manual NC-15-013, Rev A dated 10/28/16 or later FAA approved revisions.

Limitations and Conditions:

- 1. FAA approved Airplane Flight Manual Supplement, Doc No. NC-15-011, Rev A., approved October 25, 2018, or later FAA approved revision, is required to be on board the modified aircraft.
- 2. Compatibility of this design change with previously approved modifications must be determined by the installer.
- 3. A copy of this certificate must be maintained as part of the permanent records for the modified aircraft.
- 4. If the holder agrees to permit another person to use this certificate to alter the product, the holder shall give the other person written evidence of that permission.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: November 16, 2016

Date reissued: March 11, 2019

Date of issuance: December 19, 2018

Date amended:

By direction of the Administrator

Roy É. Boffo

Manager, Propulsion and

Program Management Section

Chicago ACO Branch

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.